
From: Clonts, Michael
Sent: Thursday, August 27, 2009 12:27 PM
To: 'doug.hammer@magellanlp.com'
Cc: 'Smith.Donaldp@epamail.epa.gov'; 'McKay.Tom@epamail.epa.gov'
Subject: FRP-06-AR-00053 Magellan, Ft. Smith Terminal; EPA FRP/SPCC inspection results
Attachments: FRP-06-TX-00053 FRP Checklist.pdf; FRP-06-AR-00053 SPCC Checklist.pdf; FRP-06-AR-00053 Reg. Approval.pdf

Dear Mr. Hammer:

On August 25, 2009, representatives of the U.S. Environmental Protection Agency (EPA) conducted an Oil Pollution Prevention (40 CFR Part 112) inspection at the Magellan Pipeline Co., LP, Ft. Smith Terminal located 8101 Highway 71 South, Ft. Smith, AR. The inspection included a Facility Response Plan (FRP) and Spill Prevention Control and Countermeasure (SPCC) compliance review. Results of the compliance review and deficiencies noted are attached.

Please provide to this office, within 30 days of the date of this message, documentation, photographs, etc., as necessary to clearly demonstrate that the deficiencies have been corrected, or provide a firm schedule for achieving compliance with the oil pollution regulations. If no response is received within 30 days, potential enforcement actions may follow. Please provide your response to:

Don Smith, Sr. On Scene Coordinator
U. S. Environmental Protection Agency
(6SF-PO)
1445 Ross Avenue
Dallas, Texas 75202-2733

If you have any questions regarding this correspondence, please contact Don Smith at (214) 665-6489.